

Package ‘pbcc’

October 14, 2022

Type Package

Title Percentile-Based Control Chart

Version 0.0.3

Maintainer Zsolt T. Kosztyan <kzst@gtk.uni-pannon.hu>

Description Design and implementation of Percentile-based Shewharts Control Charts for continuous data. Faraz (2019) <doi:10.1002/qre.2384>.

License GPL (>= 2)

Encoding UTF-8

URL <https://github.com/kzst/pbcc>

Depends R (>= 3.10)

Imports rgenoud, ggplot2, stats, qcc, grDevices, ggpubr

Collate 'odpbc.R' 'pbcc.R' 'plot.pbcc.R' 'summary.pbcc.R'

RoxygenNote 7.2.1

NeedsCompilation no

Author Aamir Saghir [aut],
Zsolt T. Kosztyan [aut, cre]

Repository CRAN

Date/Publication 2022-10-05 09:10:02 UTC

R topics documented:

odpbc	2
pbcc	4
plot.pbcc	6
summary.pbcc	7

Index	10
--------------	-----------

Description

Determine the optimal statistical design parameters of either individual or joint Shewharts control charts for percentile-based designs (PL) approach with guaranteed in-control and out-of-control performances.

Usage

```
odpbc(nmax,T1, T2, hv, mat, p1=0.05,p2=0.05, d=1.0, delta=1.5,
type= c("Xbar", "R", "S", "S2", "Xbar-R", "Xbar-S", "Xbar-S2"),pop.size=1000, sided="two")
```

Arguments

nmax	The maximum possible sample size in each sampling interval (a numeric value).
T1	The desired in-control time to signal (a numeric value).
T2	The desired out-of-control time to signal (a numeric value).
hv	The vector of intersample interval upto maximum T2 (a numeric vector of possible sample intervals).
mat	The matrix of minimum and maximum bounds for optimum parameters sample size and sample interval. The minimum values of n and h are (2,0.5) and maximum value are (nmax, T2).
p1	The probability to signal in-control from a specified number (default value is 5%)
p2	The probability to signal out-of-control from a specified number (default value is 5%)
d	The expected shift size in the process average in term of standrd deviation, i.e. $d= u-l-u_0 /\sigma$ (default value is 1.0). When the process is in-control w.r.t process average, set d=0.
delta	The expected shift size in the process variance (default value is 1.5). When the process is in-control w.r.t process variation, set delta=1.0
type	A character string specifying the type of Shewhart control chart either individual or joint. Available types are; "Xbar", "R", "S", "S2", "Xbar-R", "Xbar-S" and "Xbar-S2".
pop.size	Population size. This is the number of individuals genoud uses to solve the optimization problem for genetic algorithm (default value is 1000).
sided	A character string specifying the calculation of either one-sided or two-sided control limits of Shewhart dispersion charts based on PL approach (default type is two-sided).

Value

Returns the optimal parameters of PL type control chart:

n	The optimal sample size to design the percentile-based either individual or joint control chart.
h	The optimal intersampling interval to design the percentile-based either individual or joint control chart.
k	The optimal control chart constant/multiplier to design the percentile-based xbar control chart.
lp	The optimal lower percentile point of relative sample range/standard deviation/variance distribution to calculate the lower control limits of percentile-based dispersion control chart.
or/and	
up	The optimal upper percentile point of relative sample range/standard deviation/variance distribution to calculate the lower control limits of percentile-based dispersion control chart.

Author(s)

Aamir Saghir, Zsolt T. Kosztyan*
 e-mail: kzst@gtk.uni-pannon.hu

References

Faraz A, Saniga E, Montgomery D. (2019). Percentile-based control charts design with an application to Shewhart Xbar and S2 control charts. *Quality and Reliability Engineering International*, 35(1); 116-126.

See Also

[pbcc,summary.pbcc,plot.pbcc.](#)

Examples

```
# Calculation of optimal parameters of the percentile-based control charts
#using "pbcc" package.

# Set the maximum possible sample size in each h units is 10.
nmax=10

# Set the process in-control time to signal is at least 100 samples.
T1=100

# Set the control chart time to signal is at most 1 samples
# when shift occur in the process mean or/and std.dev.
T2=3
```

```

# Set the sampling intersample intervals to 0.5(0.5) T2 units of time.
hv=seq(0.5, T2, by=0.5)

#Set the lower and upper bounds of parameters(n and h) used in the optimization.
mat=matrix(c(2, nmax, 1, length(hv)), 2,2, byrow=TRUE)
p1=0.05 # Set the probability of guaranteed in-control signals is 5%.
p2=0.05 # Set the probability of guaranteed out-of-control signals is 5%.

# Optimal parameters of two-sided percentile-based Xbar control chart.

d=3 # Set the shift size in the process mean is 3 (large shift).
Q1<- odpbc(nmax, T1, T2, hv, mat, p1, p2, d, delta=1.5, type= "Xbar")

# Optimal parameters of one-sided percentile-based variance control chart.

delta=2 # Set the shift size in the process dispersion is 2 (moderate shift).
Q2<- odpbc(nmax, T1, T2, hv, mat, p1, p2, d=1.0, delta, type= "S2", sided="one")

#Optimal parameters of two-sided percentile-based joint Xbar& S control chart.
d=1.0 # Set the shift size in the process mean is 1 (small shift).
delta=2 # Set the shift size in the process dispersion is 2 (moderate shift).
Q3<- odpbc(nmax, T1, T2, hv, mat, p1, p2, d, delta, type= "Xbar-S")

```

pbc

Package of Percentile-based Control Charts

Description

Create an object of class 'pbcc' to perform statistical quality control based on percentile-based designs (PL) approach. This object may then be used to plot percentile-based Shewhart charts either individual or joint and summary statistics with guaranteed in-control performance. Also, it determine the optimal parameters n (sample size), h (sampling interval), k (control chart constant) for average chart, l_p and u_p (lower and upper percentiles of the relative range/std.dev/variance distribution) for Statistical Design of Percentile-based control charts.

Author(s)

Aamir Saghir, Zsolt T. Kosztyan*
e-mail: kzst@gtk.uni-pannon.hu

References

Faraz A, Saniga E, Montgomery D. (2019). Percentile-based control charts design with an application to Shewhart Xbar and S2 control charts. *Quality and Reliability Engineering International*, 35(1); 116-126.

See Also

[pbcc](#), [odpbc](#), [summary.pbcc](#), [plot.pbcc](#).

pbcc *Percentile-based control charts*

Description

Create an object of class 'pbcc' to perform statistical quality control based on percentile-based designs (PL) approach. This object may then be used to plot percentile-based Shewhart charts either individual or joint, summary statistics and more with guaranteed in-control performance.

Usage

```
pbcc(data,T1,p1,type=c("Xbar","R","S","S2","Xbar-R","Xbar-S","Xbar-S2"),sided="two")
```

Arguments

data	A data frame, a matrix or a vector containing observed data for the variable to chart. Each row of a data frame or a matrix, and each value of a vector, refers to a sample or "rationale group".
T1	The desired in-control time to signal (a numeric value, default value is 100).
p1	The probability to signal in-control from a specified number (a numeric value, default value is 5%)
type	A character string specifying the type of Shewhart control chart either individual or joint. Available types are; "Xbar", "R", "S", "S2", "Xbar-R", "Xbar-S" and "Xbar-S2".
sided	A character string specifying the calculation of either one-sided or two-sided control limits of Shewhart dispersion charts based on PL approach (default type is two-sided).

Value

Returns an object of class 'pbcc' with "data.name", "type" and values of "sizes", "std.dev", "statistics" and "control limits" of individual or joint Shewhart control chart.

Author(s)

Aamir Saghir, Zsolt T. Kosztyan*
e-mail: kzst@gtk.uni-pannon.hu

References

Faraz A, Saniga E, Montgomery D. (2019). Percentile-based control charts design with an application to Shewhart Xbar and S2 control charts. *Quality and Reliability Engineering International*, 35(1); 116-126.

See Also

[odpbc](#), [summary](#), [plot](#).

Examples

```
#Calculation of the percentile-based control charts using "pbcc" package for
# "diameter" of pistonrings data.
library(qcc)
data(pistonrings)
diameter = with(pistonrings, qcc.groups(diameter, sample))
T1=100      # Set the process in-control time to signal is at least 100 samples.
p1=0.05     # Set the probability of guaranteed in-control signals is 5%.

#Calculation of two-sided individual percentile-based Xbar control chart
#for diameter data.
Q11<- pbcc(diameter,T1, p1, type="Xbar")

# Calculation of One-sided individual percentile-based S2 control chart
# for diameter data.
Q12<- pbcc(diameter,T1, p1, type="S2", sided="one")

# Calculation of two-sided joint percentile-based Xbar and S control chart
#for diameter data.
Q13<- pbcc(diameter,T1, p1, type="Xbar-S", sided="two")
```

plot.pbcc

Plot function for Percentile-based Control Charts

Description

Plot function for the Package of Percentile-based Control Charts (pbcc)

Usage

```
## S3 method for class 'pbcc'
plot(x, title,...)
```

Arguments

x	an object of class 'pbcc'.
title	title of the plot
...	other graphical parameters.

Value

No return value, called for side effects

Author(s)

Aamir Saghir, Zsolt T. Kosztyan*
e-mail: kzst@gtk.uni-pannon.hu

References

Faraz, A., Saniga, E., Montgomery, D. (2019). Percentile-based control chart design with an application to Shewhart Xbar and S2 control charts. *Quality and Reliability Engineering International*, 35(1),116-126.

See Also

[pbcc](#), [odpbc](#), [summary](#).

Examples

```
library(qcc)
data(pistonrings)
diameter = with(pistonrings, qcc.groups(diameter, sample))
T1=100      # Set the process in-control time to signal is at least 100 samples.
p1=0.05     # Set the probability of guaranteed in-control signals is 5%.

#Calculation of two-sided individual percentile-based Xbar for diameter data.
Q11<- pbcc(diameter,T1, p1, type="Xbar")
# Plot two-sided individual percentile-based Xbar for diameter data.
plot(Q11)

# Calculation of One-sided individual percentile-based S2 for diameter data.
Q12<- pbcc(diameter,T1, p1, type="S2", sided="one")
## Plot one-sided individual percentile-based S2 for diameter data.
plot(Q12)

# Calculation of two-sided joint percentile-based Xbar and S for diameter data.
Q13<- pbcc(diameter,T1, p1, type="Xbar-S", sided="two")
# Plot two-sided joint percentile-based Xbar-S control chart for diameter data.
plot(Q13)
```

summary.pbcc

Print statistics,summary of statistics,control limits,optimal design parameters.

Description

Print statistics, summary of statistics, control limits, optimal design parameters of Percentile-based control charts with guaranteed in-control or/and out-of-control performances.

Usage

```
## S3 method for class 'pbcc'
summary(object, digits = getOption("digits"), ...)
## S3 method for class 'odpbc'
summary(object, digits = getOption("digits"), ...)
```

Arguments

object an object of class 'pbcc' or 'odpbc'.
 digits the number of significant digits to use when add.stats = TRUE.
 ... additional arguments affecting the summary produced.

Value

No return value, called for side effects

Author(s)

Aamir Saghir, Zsolt T. Kosztyan*
 e-mail: kzst@gtk.uni-pannon.hu

References

Faraz, A., Saniga, E., Montgomery, D. (2019). Percentile-based control chart design with an application to Shewhart Xbar and S2 control charts. *Quality and Reliability Engineering International*, 35(1),116-126.

See Also

[pbcc](#), [odpbc](#), [plot](#).

Examples

```
# Print summary of calculation of two-sided individual percentile-based xbar
# control chart for diameter data with guaranteed in-control performance.

library(qcc)
data(pistonrings)
diameter = with(pistonrings, qcc.groups(diameter, sample))
T1=100      # Set the process in-control time to signal is at least 100 samples.
p1=0.05     # Set the probability of guaranteed in-control signals is 5%.

#Calculation of two-sided individual percentile-based Xbar for diameter data.
Q11<- pbcc(diameter,T1, p1, type="Xbar")
summary(Q11) # summarize the results

# Print summary of Calculation of two-sided joint percentile-based Xbar
# and S control chart for diameter data with guaranteed in-control performance.
# Calculation of two-sided joint percentile-based Xbar and S for diameter data.
Q13<- pbcc(diameter,T1, p1, type="Xbar-S", sided="two")
summary(Q13) # summarize the results

# Print summary of optimal design parameters of percentile-based Xbar chart
# with guaranteed in-control and out-of-control performances.
nmax=10     # Set the maximum possible sample size in each h units is 10.
T1=100     # Set the process in-control time to signal is at least 100 samples.
```

```
# Set the control chart time to signal is at most 1 samples when shift occur
#in the process mean or/and std.dev.
T2=3
# Set the sampling intersample intervals to 0.5(0.5) T2 units of time.
hv=seq(0.5, T2, by=0.5)
#Set the lower and upper bounds of parameters(n and h) used in the optimization.
mat=matrix(c(2, nmax, 1, length(hv)), 2,2, byrow=TRUE)
p1=0.05      # Set the probability of guaranteed in-control signals is 5%.
p2=0.05      # Set the probability of guaranteed out-of-control signals is 5%.
d=3          # Set the shift size in the process mean is 3 (large shift).
Q1<- odpbc(nmax, T1, T2, hv, mat, p1, p2, d, delta=1.5, type= "Xbar")
summary(Q1) # summarize the results

# Summary of percentile-based design of joint xbar and s chart with guaranteed
#in-control and out-of-control performances.
d=1.0        # Set the shift size in the process mean is 1 (small shift).
delta=2      # Set the shift size in the process dispersion is 2 (moderate shift).
Q3<- odpbc(nmax, T1, T2, hv, mat, p1, p2, d, delta, type= "Xbar-S")
summary(Q3) # summarize the results
```

Index

- * **Shewhart**

- plot.pbcc, 6

- summary.pbcc, 7

- * **control chart**

- odpbc, 2

- pbcc, 5

- plot.pbcc, 6

- summary.pbcc, 7

- * **package**

- pbc, 4

odpbc, 2, 4, 5, 7, 8

pbc, 4

pbcc, 3, 4, 5, 7, 8

plot, 5, 8

plot.pbcc, 3, 4, 6

summary, 5, 7

summary.odpbc (summary.pbcc), 7

summary.pbcc, 3, 4, 7